

N
▲

0 150 300 Feet

Prepared by BRP	Checked by DRP
-----------------	----------------

Legend


 Seismic Survey Line Locations

Figure 3-3
Seismic Survey Line Locations

Remedial Investigation Report
Stratford Army Engine Plant
Stratford, Connecticut

— MACTEC Engineering and Consulting, Inc.